B. Tech Degree IV Semester (Special Supplementary) Examination, March 2007

EE 405 ELECTRICAL MACHINES I

(1999 Admissions Onwards)

Time: 3 Hours Maximum Marks: 100

(All questions carry **EOUAL** marks)

- I. (a) What is the principle of operation of a dc generator? Why is a commutator and brush arrangement necessary for the operation of a dc generator?
 - (b) A 4 pole lap wound shunt generator supplies to 50 lamps of 100 watts, 200 V each. The field and armature resistances are 50Ω and 0.2Ω respectively. Allowing a brush drop of 1V per each brush, calculate the following: (i) Armature current (ii) Current per path (iii) Generated emf.

OR

- II. (a) Derive the emf equation of a dc generator.
 - (b) A 4 pole generator supplies a current of 143 A. It has 492 armature conductors —

 (i) wave wound (ii) lap wound. When delivering full load, the brushes are given an actual lead of 10°. Calculate the demagnetizing ampere-turns per pole. The field winding is shunt connected and take 10 A. Find the number of extra shunt field turns to neutralize the demagnetization.
- III. (a) Enumerate the reasons which cause terminal voltage under load conditions to be different from the terminal voltage under no load conditions for dc shunt generator.
 - (b) A separately excited dc generator running at 1000 rpm gave the following o c c:-

Field current (A) -	1.2	2,4	3.6	5.0	6.2	7.4
EMF (V) -	140	280	375	440	490	520

Calculate -

- (i) The voltage developed when the machine is excited as a shunt generator with a field resistance of 80Ω at 1000 rpm.
- (ii) The speed at which the machine just fails to excite.
- (iii) The additional resistance which should be inserted in the field circuit to reduce the voltage to 360 V at 1000 rpm.

OR

- IV. (a) Draw and explain the external characteristics of shunt, series and compound generators.
 - (b) Two DC shunt generators with emfs of 120 V and 115 V, armature resistances of 0.05Ω and 0.04Ω and field resistances of 20Ω and 25Ω respectively are in parallel supplying a total load of 25 KW. How do they share the load?
- V. (a) Draw the characteristics of dc shunt and series motors. Use these curves to explain the applications for which these motors are used.

(Turn Over)



(b) A 4 - pole 250 V, wave connected shunt motor gives 10 KW when running at 1000 rpm and drawing armature and field currents of 60 A and 1 A respectively. It has 560 conductors. Its armature resistance is 0.2 Ohm. Assuming a drop of 1 V per brush. Calculate --

(i) Total torque

(ii) Useful torque

(iii) Useful flux/pole

(iv) Rotational losses

(iv) Efficiency.

OR

- VI. (a) Describe how a swin burne's test is conducted on DC machines. State its advantages and disadvantages.
 - (b) A 10 KW, 240 V, dc shunt motor draws a line current of 5.2 A while running at no load speed of 1200 rpm from a 240 DC supply. It has an armature resistance of 0.25Ω and a field resistance of 160Ω . Estimate the efficiency of the motor when it delivers rated load.
- VII. (a) Draw the phasor diagram of the transformer on lagging pf load and explain it.
 - (b) The high voltage and low voltage winding of a 2200/220 V single phase 50 Hz transformer has resistances of 4.8Ω and 0.04Ω and reactances 2Ω and 0.018Ω respectively. The low voltage winding is connected to a load having an impedance of $(6+j4)\Omega$. Determine
 - (i) Current in l.v. winding and h.v. winding
 - (ii) Load voltage
 - (iii) Power consumed by the load.

OR

- VIII. (a) Develop the equivalent circuit of a single phase transformer.
 - (b) A single phase transformer is connected to a 230 V, 50 Hz supply. The net cross sectional area of the core is 60 cm². the number of turns in the primary is 500 and in the secondary is 100. Determine: (i) Transformation ratio (ii) Emf induced in the secondary winding (iii) Maximum value of flux density in the core.
- IX. (a) Explain with circuit diagrams, the open circuit and short circuit tests to be carried out in the laboratory for the determination of parameters of a single phase transformer.
 - (b) The following readings were obtained from OC and SC tests on 8 KVA 400/120 V 50 Hz transformer:

OC test

: 120 V, 4 A, 75 W

SC test

: 9.5 V, 20 A, 110 W.

Calculate -

- (i) Voltage regulation and efficiency for 0.8 pf lagging, full load
- (ii) The efficiency at half full load 0.8 pf lagging load.

OR

X. (a) Write short notes on:

- (i) Y Y connections
- (ii) V-V connection.
- (b) Two single phase transformers with equal turns have impedance of (0.6+j4) and $(0.8+j10)\Omega$ with respect to the secondary. If they operate in parallel determine how they will share total load of 120 KW at 0.8 pf lagging.
