



ENGINEERING & MANAGEMENT EXAMINATIONS, JUNE - 2009
ELECTRICAL MACHINE DESIGN
SEMESTER - 6

Time : 3 Hours]

[Full Marks : 70

GROUP - A**(Multiple Choice Type Questions)**1. Choose the most appropriate alternative for any ten of the following : $10 \times 1 = 10$

i) The core section of a large capacity transformer is

- | | | |
|----------------|----------------|--------------------------|
| a) cruciform | b) rectangular | |
| c) multisteped | d) circular. | <input type="checkbox"/> |

ii) The air gap of a polyphase induction motor is kept small to

- | | |
|-----------------------------------|--------------------------|
| a) reduce possibility of crawling | |
| b) reduce the noise | |
| c) reduce the magnetizing current | |
| d) obtain high starting torque. | <input type="checkbox"/> |

iii) Coils used in loading rheostats are made up of

- | | | |
|--------------------|--------------------|--------------------------|
| a) Iron-Constantan | b) Nichrome | |
| c) Copper | d) both (a) & (b). | <input type="checkbox"/> |

iv) When a 3- ϕ induction motor is designed with higher value of B_{av} , it will give

- | | | |
|--------------------------------|------------------------------|--------------------------|
| a) high full load pf | b) a higher starting torque | |
| c) higher full load efficiency | d) higher overload capacity. | <input type="checkbox"/> |

v) The least desired property of a magnetic material for making electrical machines is

- | | | |
|--------------------------------|-------------------------------|--------------------------|
| a) high electrical receptivity | b) high magnetic permeability | |
| c) low loss co-efficient | d) large hysteresis loop. | <input type="checkbox"/> |



- vi) The leakage reactance of a transformer is
- a) directly proportional to number of turns
 - b) directly proportional to square of number of turns
 - c) inversely proportional to the number of turns
 - d) inversely proportional to the square of number of turns.
-
- vii) The maximum permissible temperature for class A insulation is
- a) 90°C
 - b) 105°C
 - c) 155°C
 - d) 180°C.
-
- viii) Carter's co-efficient is applied to estimate
- a) requirement of air gap *mmf*
 - b) flux distribution in air gap
 - c) length of air gap
 - d) no load loss.
-
- ix) If a transformer is to be designed for minimum total cost, the condition is
- a) cost of iron must be equal to the cost of conductor
 - b) weight of iron is equal to the weight of conductor
 - c) iron loss is equal to the I^2R loss in conductor
 - d) volume of iron is equal to the volume of conductor.
-
- x) A large value of ampere conductors per metre means
- a) greater amount of copper is used in the machine
 - b) space required for insulation is less
 - c) less number of turns per phase
 - d) less temperature rise.
-
- xi) In choke used in series with a discharge lamp, the voltage drop across the choke is
- a) inversely proportional to area of core
 - b) proportional to the average flux density in Wb/m^2
 - c) inversely proportional to supply frequency
 - d) inversely proportional to the number of turns in the choke coil.
-
- xii) In case of induction motor, the average value of air gap flux density taken is
- a) 1.2 to 1.5 tesla
 - b) 0.7 to 1.0 tesla
 - c) 0.3 to 0.6 tesla
 - d) 0.1 to 0.2 tesla.
-

**GROUP - B****(Short Answer Type Questions)**Answer any *three* of the following.

3 × 5 = 15

2. With reference to induction motor, discuss the meaning of the following :
 - i) Specific electric loading
 - ii) Specific magnetic loading.
3. What are the factors that limit the design of an electric machine ?
4. a) Define specific permeance.
b) Mention principal components of armature leakage flux.
5. A plunger type magnet has to lift a mass of 150 kg from a distance of 10 mm. The area of pole face is $5 \times 10^{-3} \text{ m}^2$. Find the current required if the excitation coil has 3000 turns. Assume that the *mmf* required for iron parts = 10% of air gap *mmf*. Neglect fringing.
6. A 250 V, 1.5 kW single element electric furnace is to employ a nichrome resistance wire operating at 1000°C. Estimate a suitable diameter of the wire. Take radiating efficiency = 1, emissivity = 0.9 & the resistivity of wire = 0.424 Ωm at 1000°C.

GROUP - C**(Long Answer Type Questions)**Answer any *three* questions.

3 × 15 = 45

7. a) Design an iron cored choke to be connected to 230 volt a.c. supply (50 Hz) & suitable for 5 amp inductive current.
b) i) What are the types of electromagnets ?
ii) Which types of materials are used in the core of electromagnets ? 10 + 5
8. Determine the approximate diameter & length of the stator core, the number of stator slots & the number of conductors for a 11 kW, 400 V, 3-phase, 4-pole, 1425 rpm delta connected induction motor. Adopt a specific magnetic loading of 0.45 Wb/m & a specific electric loading of 23,000 A/m. Assume full load efficiency & power factor as 0.85 & 0.88 respectively. The ratio of core length to pole pitch is 1. The stator employs a double layer winding.



9. a) What are the different methods of cooling of transformers ?
- b) Develop the expression for the output kVA ' Q ' of a single phase transformer involving frequency, flux density, current density, core window area and net core area.
- c) Calculate the dimensions for core & yoke for a 5 kVA, 50 Hz, single phase core type transformer. A rectangular core is used with long side twice as long as short side. The window height is 3 times the width. Voltage per turn is 1.8 V, space factor 0.2, current density 1.8 A/mm², flux density 1 Wb/m². 3 + 5 + 7
10. a) Calculate the expression for magnetizing current for the following :
- i) Concentrated winding
- ii) Distributed winding with sinusoidal flux distribution.
- b) Calculate the specific iron loss in a specimen of alloy steel for a maximum flux density of 3.2 Wb/m² & a frequency of 50 Hz using 0.5 mm thick sheets. The resistivity of alloy steel is 0.3×10^{-6} Ω m. The density is 7.8×10^3 kg/m³. Hysteresis loss in each cycle is 400 J/m³. 8 + 7
11. Write short notes on any *three* of the following : 3 × 5
- a) Modern trends in design of electric machine.
- b) Bushing & transformer insulation.
- c) Design of capacitors for power system.
- d) Core design of 3-phase transformer.

END