SATHYABAMA UNIVERSITY

(Established under section 3 of UGC Act, 1956)

Course & Branch: B.E – EEE

Title of the paper: Computer Aided Design

Semester: V Max.Marks: 80 Sub.Code: 414507 Time: 3 Hours Date: 04-05-2009 Session: AN

PART - A (10 x 2 = 20) Answer All the Questions

- 1. What is the acronym for MATLAB and VHDL?
- 2. Write the syntax of format function with an example.
- 3. Mention the advantages of M-File scripting.
- 4. Debug the following code:

```
t= -pi:pi/100:pi;
y= sin(t);
plot(t,y,-r);
axis ([-pi pi -1 1]);
xlabel (""\pi \leg \\itt\ \leg \\pi");
ylabel ('sin(t)';
```


- 5. Write an M-file to simulate and plot an ideal half wave rectifier with $v(x) = 12 \sin(x)$.
- 6. What is meant by closed-loop simulation? Mention their advantages.
- 7. What are the standard IEEE libraries used in VHDL coding?

- 8. What are physical types of data? Give an example.
- 9. Why we go for VHDL for real time design and simulation of digital system?
- 10. What is a Test bench in VHDL?

PART – B
$$(5 \times 12 = 60)$$

Answer All the Questions

- 11. Write M-files to
 - (a) Generation 5x5 random matrix.
 - (b) Solve the quadratic equation.
 - (c) Scalar multiplication of matrices.
 - (d) Generate first 10 Fibonacci numbers. (4x3=12) (or)
- 12. (a) Explain in detail about the colon (:) operator with an example.
 - (b) Draw the mesh plot for sinc function using plotting command in MATLAB?
- 13. For the given RLC series network,



Develop the MATLAB-Simulink model for obtaining the time response characteristics of the system.

- 14. Write M-File for simulation of n-point DFT using Cooley-Tukey algorithm (FFT) with two radix butterfly as its basic function.
- 15. Assume that a BJT has an emitter area of 5.0mil^2 , $\beta_F = 120$, $\beta_R = 0.3$, transport current density, $J_S = 2 \times 10^{-10} \, \mu\text{A/mil}^2$ and $T = 0.3 + 10^{-10} \, \mu\text{A/mil}^2$

300K. Plot I_E versus V_{BE} for V_{BC} = -1V using MATLAB. Assume $0 < V_{BE} < 0.7 \text{ V}$, $q=1.602 \times 10^{-19}$.

(or)

16. For the circuit shown in Fig.1, use MATLAB to find the poles and zeros. Plot the magnitude and phase response, assume that C1 = 0.1 uF, $C2 = 1000 \ 0.1 \text{uF}$, R1 = 10 K, and $R2 = 10 \Omega$.




Fig.1

Transfer function

- 17. (a) Describe about mixed style modeling and implement Full adder with mixed style model of VHDL.
 - (b) Briefly explain about assertion statement with raising edge triggered D flip-flop as its example.

(or)

- 18. Design a 4-bit ALU unit of a microprocessor with
 - (a) Carry and borrow overflows
 - (b) Signed and unsigned overflows
 - (c) All basic arithmetic and logical operations
 - (d) Increment and decrement operations using VHDL coding
- 19. (a) Explain briefly about operator overloading with an example.
 - (b) Write down the steps to create the user defined libraries.

(or)

- 20. (a) Write VHDL code to find largest of two 8-bit binary number. (5)
 - (b) What are the Effects of Transport delays on signal drivers? (3)
 - (c) Write steps to create a state machine using VHDL. (4)