## SATHYABAMA UNIVERSITY

(Established under section 3 of UGC Act, 1956)

Course & Branch: B.E – EEE/ETCE

Title of the paper: Measurements and Instrumentation

Semester: IV
Sub.Code: 6C0096
Time: 3 Hours
Date: 17-11-2008
Session: AN

## PART – A

 $(10 \times 2 = 20)$ 

## Answer All the Questions

- 1. What is the need for measurement?
- 2. Write the need for calibration.
- 3. What two conditions must be satisfied to make an ac bridge balance?
- 4. Define Transducers. Bring out the advantages of electric transducers.
- 5. State any four advantages of digital instruments over analog instruments.
- 6. What is a self balancing potentiometer? Where it is used?
- 7. How are the digital voltmeter classified?
- 8. What is the advantage of "pre trigger view" mode of operation in DSO?
- 9. Give any two applications of wave analyzer.
- 10. List the controllers normally found on XY recorder.

## PART - B (5 x 12 = 60) Answer All the Questions

11. Describe in detail the different types of dynamic errors in a measurement system.

(or)

- 12. Draw the block diagram of a function generator and explain the method of producing sine waves.
- 13. Draw the circuit of a wheat stone bridge and explain how medium resistances are measured using the same.

(or)

- 14. What is temperature transducer? How are they classified and explain any one in detail?
- 15. With a neat diagram explain the various parts of CRO.

(or)

- 16. With a neat diagram, explain the construction, working, torque equation and advantages and disadvantages of a PMMC instrument.
- 17. With a neat sketch discuss how the waveform is stored in digitized format in a DSO.

(or)

- 18. (a) With neat sketches explain the measurement of time interval and pulse width.
  - (b) Write short notes on the accuracy of digital meters.
- 19. Define spectrum analysis and explain the working of basic spectrum analyzer with a block diagram.

(or)

20. What are the various classifications of recorders and explain galvanometer type strip chart recorder with a neat diagram.