## B. Tech Degree IV Semester Examination, April 2010

## ME 402 METALLURGY AND MATERIAL SCIENCE

(2002 Scheme)

	Time: 3	Hours	Maximum Marks:	100
	I.	(a)	What is a metallic bond? How does the type of bonding influences the properties of	(T)
		(b)	crystals? Distinguish between a family of planes and family of directions.  Prove that FCC is closely packed than BCC by calculating atomic packing factor for	(7)
			both.	(7)
		(c)	Discuss the importance of dislocations. Differentiate between edge and screw dislocation.	(6)
			OR	(0)
	II.	(a)	Explain the process of solidification of metals to form polycrystalline structure.	
		(-)	What are the parameters which control the grain size on solidification?	(7)
		(b)	Substantiate the following statements:	
			(i) The electrical conductivity of ionic bonded solids is poor.	(7)
		4.5	(ii) Crystalline materials exhibit sharp freezing point.	(7)
		(c)	What is Burgers vector? Draw the burgers circuits for perfect and imperfect crystals and explain.	(6)
			and explain.	(0)
	Ш.	(a)	What are the factors that effect the formation of substitutional and interstitial solid	
		` '	solution?	(7)
		(b)	Explain the importance of equilibrium diagrams in the development of new alloys.	(7)
		(c)	Draw Cu-Ni phase diagram and indicate the phases, temperatures and compositions.  OR	(6)
	IV.	(a)	Draw and label various areas of an isomorphous system (phase diagram) in which two	(10)
		(L)		(10)
		(b)	Explain the application of phase rule with suitable examples. Discuss the eutectoid reaction in steel.	(10)
			reaction in Secti.	()
	V.	(a)	Sketch the TTT diagram of the following and explain their salient points:-	
			(i) medium carbon steels (ii) high carbon steel	
				(10)
P)		(b)	Why non ferrous metals are not usually considered suitable for heat treatment? How	(10)
$\langle \cdot \rangle$	<b>်\</b>		they are heat treated?  OR	(10)
12	<u>₩</u>	(a)	Discuss briefly the different techniques of surface hardening of steel and mention their	
200	[5]	()		(10)
31	[\$]	(b)	Define hardenability. How is it assessed? Describe a method for determining	
Źί	G. (1.66)		hardenability of steel.	(10)
		(-)	Show have Cuiffish's areal, theory explains the considerable offerts, which the presence	
	VII.	(a)	Show how Griffith's crack theory explains the considerable effects, which the presence of microstructure faults has a stress raisers in a metal in tension. Why is C4 weak in	
				(10)
		(b)	Explain how will you proceed to stop a crack just propagated in a metal. Give the	. ,
			reasons to do so, what would be the stress at the crack tip.	(10)
			OR	
	VIII.	(a)	Describe the kind of fracture, which may occur in a propeller shaft of an automobile.	(7)
		(b)	Explain the type of failure if a tool mark left on the surface of a component in the view of crack initiation and propagation.	(7)
		(c)	Justify the statement "pure metals can be effectively strengthened only by cold working"	(7) (6)
		(0)	bushing the successful pare means out of encourage successful and only of cold working	(0)
	IX.	(a)	Discuss the effect of alloying elements on steels. State the materials used for the following  (i) Hack saw blades	g :-
			(ii) Permanent magnets	(7)
		(b)	What are the important casting alloys of aluminium? Give their composition and uses.	C)
		• •	What are the bearing materials?	(7)
		(c)	Why stainless steels are corrosion resistant?	(6)
	47	4.5	OR	(7)
	X.	(a)	Classify cast iron and indicate their microstructures and their applications.  What are the materials used for medical services and explain?	(7)
		(b) (c)	What are the properties of pure copper. Write a note on high alloy steels.	(6) (7)
		(~)	11 time and and brobes man or hard sobbar. 11 time a more on mon amore and	マナ